From:
 victor.a.schneider@cummins.com

 To:
 Gregory Orehowsky/DC/USEPA/US@EPA

Cc: jeff.w.lewis@cummins.com; wayne.eberhard@cummins.com

**Subject:** Re: 313c face plugging **Date:** 01/08/2008 01:30 PM

. .

The midrange ISB and ISL families with the higher NOx levels (8CEXH0408BAC, 8CEXH0408BAD, 8CEXH0540LAL) have less use of the face-plugging AECD compared to the lower NOx families because of the less engine-out PM and smoke from these engines resulting in less frequent regeneration events of dosing which causes the face-plugging.

Orehowsky.Gregory@epamail.epa.gov

To victor.a.schneider@cummins.com

CC

01/08/2008 12:35 PM

Subject Re: 313c face plugging

Looks like 313d is the same.

Greg Orehowsky Compliance and Innovative Strategies Division Office of Transportation and Air Quality Phone: 202-343-9292 Fax: 202-343-2804

> victor.a.schneid er@cummins.com

01/08/2008 12:32 Gregory Orehowsky/DC/USEPA/US@EPA
PM GC

Re: 313c face plugging Subject

We're looking into this...

Orehowsky.Gregory@epamail.epa.gov

01/08/2008 12:01 PM

To victor.a.schneider@cum mins.com

CC

Subject 313c face plugging

ED\_002669D\_00002279-00001

Compliance and Innovative Strategies Division Office of Transportation and Air Quality Phone: 202-343-9292 Fax: 202-343-2804

This email has been scanned by the MessageLabs Email Security System. For more information please visit http://www.messagelabs.com/email

This email has been scanned by the MessageLabs Email Security System. For more information please visit http://www.messagelabs.com/email